


IC-001: Flexible Reference Electrode



Use:

1. This electrode is prefilled with reference solution.
2. Connect the alligator clip of this reference electrode to either the outer shell of the BNC connector or to the ground of the meter.

Maintenance:

1. If refilling is required: Remove the luer cap, inject provided reference solution into the tee fitting, and then close the luer cap.
2. After each use, rinse the tip in distilled water and store dry.